



# Watertight

Bathroom & Kitchen Re-piping and Renovations  
High Water Account Investigations  
Geyser Valve Replacements  
Leak Detection and repairs  
Burst Geysers  
Pipe Relining  
Plumbing



First National Battery experienced a serious problem with their sewer line which runs under the building. The manhole was also under the building and access was a problem.

**Watertight Leak Detection and Pipe Relining** were called in by plumbers who had no solution for the serious problem. Watertight assessed the problem and discovered that the earthenware pipe had collapsed. Two pipe bursting companies refused to work on this problem as it deemed to be too risky. Watertight was left to reform the pipe and pulled in a cure-in-place structural liner which solved the problem!

The end result was a very happy customer!

## *The Leak Detection, Plumbing & Pipe Relining Company*

Wayne Pletschke  
083 407 7482

011 969 1728  
rpletschke@telkomsa.net

Renee Pletschke  
084 521 0505

[www.watertight.co.za](http://www.watertight.co.za)



<https://www.facebook.com/WatertightLeakDetectionAndPlumbing>