

Cure in Place Pipe Relining at the World Renowned Sun International Resort







The Clam water feature at the world famous hotel, The Palace, was inoperative due to massive water losses experienced over a number of years caused by leaking pipes.

Watertight Leak Detection and Pipe Relining was awarded the contract to reline the pipes. As the tourists were freely enjoying the resort, our staff continued to work without any disruptions to the staff or tourists. The pipes were successfully relined and as a result we have a Clam Water Feature spilling a wall of water over the edge for the first time in a number of years.

The end result was a very happy customer!

The Leak Detection, Plumbing & Pipe Relining Company

Wayne Pletschke 083 407 7482 www.watertight.co.za 011 969 1728 rpletschke@telkomsa.net



https://www.facebook.com/ WatertightLeakDetectionAndPlumbing

Renee Pletschke

084 521 0505